

Tank Performance “Under Fire”

Keys to keep your fire suppression storage systems in-service with long-life, operating safely, and ready to perform when it counts.

By David Oveson

CST, Kansas City, Missouri, is a storage tank manufacturer with roots dating back to 1893 that has been supplying tanks for decades for fire protection systems at varied sites like distribution warehouses, military bases, retail stores, power plants, oil refineries, manufacturing plants, industrial parks, hospitals, and schools, to name just a few.

CST, while manufacturing new storage tanks, also works with owners, operators, and contractors to drive home the importance of staying ahead of the curve with their fire-safety systems, which, of course, includes existing storage tanks.

Whether a system is operating in a public or private sector, it is mission-critical for protecting facilities and, certainly, its occupants and visitors. Through a robust and regular inspection process by qualified professionals, property owners can ensure their suppression systems will perform as designed to detect fires immediately, activate early-warning alarms, and ultimately extinguishing active fires.

NFPA 25 *Inspection, Testing and Maintenance of Water-Based FP Systems* provides the guidelines to help owners, and the property managers working on behalf of owners, clearly understand when an “in-house” inspection is adequate or when it is prudent to reach out to specialized fire protection contractors and inspection service experts.

Storage tanks that supply and support a fire suppression system are a major part of that equation. In some cases, a limited or non-existent inspection and preventative maintenance program may not adequately identify issues that might be fairly manageable if corrected early-on. If left unattended or not monitored appropriately, a sub-standard inspection program can lead to diminished life-span of the tank(s) and may result in issues that require taking tanks off-line for extended periods of time for substantial repair, and could, ultimately, require premature replacement with a new tank. Certainly, tanks have a life-span like any other equipment, but attention to detail can maintain the integrity of the asset and maximize the years of service.

Typically, a professional inspection service can identify issues with existing systems, and can also identify areas that might be non-compliant or not optimum design-wise vs. only reviewing what is already in-place. Suggestions on how to improve the system can then be discussed.

“A complete inspection of your storage tank should take many things into consideration and not just the storage tank



Protect your Investment: A fire protection tank is a primary asset to a facility, and critical to the success of a fire suppression system. A robust and documented inspection and maintenance program can help assure many years of “at-the-ready” service life.

only,” explains Tom DeDonder, VP of Construction Services of CST. “While the condition of the hardware, gasket, welds, and the integrity of the coating and structural components are of critical importance, there are many items like relief vents, nozzles, anchors, the foundation, insulation, heaters, etc., that are vital for the tank to operate safely. So, it’s imperative to identify issues early-on before they develop into a problem.”

“The integrity of handrails, rungs, swing-gates, cages, or step-off areas can be compromised without proper maintenance by the owner/operator, and these should be dealt with immediately to keep your operators and facility personnel safe and prevent lost-time incidents. Items like ladders, platforms, and walkways can be among the most critical ‘non-storage’ life-safety components of any tank.”

“When it is time for a full inspection of the tank, you really should consider utilizing a company that has many years of experience building tanks and supporting customers in the fire suppression market,” DeDonder adds. “Tanks that have been in service for many years might not have had the proper attention, but a good inspector can identify potential issues and not only look at the tank component that is right in front of them, but

also anticipate how it may affect the entire FP system in the future.”

DeDonder went on to detail that it is critical to maintain the records of the inspection and maintenance program, so an owner/operator can plan for the required NFPA inspections with the least impact on their facility as possible.

“There is no convenient time for inspections with any equipment,” he says, “but the inconvenience is certainly much greater when you have a systems-failure and an unplanned shut-down, or even a forced outage by a fire marshall or other compliance officer. The key is to plan ahead!”

CST was a pioneer in storage tanks beginning in 1893 (as Columbian Steel Tank). CST was the first to apply glass-fused-to-steel enameling technology to tanks in the 1940s (as A. O. Smith) and was one of the first to factory-coat tanks with epoxy in 1978 (as Columbian TecTank). CST tanks meet or exceed NFPA, FM, USACOE, and many other industry standards. CST offers full NFPA tank inspection and repair services as well.

CST has over 250,000 coated tanks deployed world-wide in over 120 countries storing a variety of liquid and dry products. For more information visit: www.cstindustries.com.

About the Author:

David Oveson is Regional Sales Manager Liquid Gulf Coast and has been with CST for over 11 years. He currently manages the Gulf Coast and Southeast Regions as well as the Caribbean. Prior to this, he was responsible for the 13 western states, including Hawaii and Alaska. His knowledge and experience with bolted tanks is extensive, and he has been

involved in the Wastewater, Fire Protection, Oil and Gas, and Municipal Water markets for the duration of his time with CST. He is based out of Houston, Texas.



For more information contact: Kimberly Mathis, Global Marketing Director, CST Industries, Inc., 498 N Loop 336 E, Conroe, TX 77301; (713) 351-3769, kmathis@cstindustries.com.



Tank without proper inspection program: Close inspection on the external parts of a tank that has been in the field for some time can present visible rust at seams, degraded gasket material, visible bowing in steel, signs of leakage, and rusted out bolts (shown here on the bottom ring).

CST STORAGE FIRE PROTECTION STORAGE SYSTEMS

- > World-Class Coatings with OptiBond™ Coating Process
- > 123+ Years of Experience
- > EMR Rate of .71
- > 350,000 Installations in over 125 Countries



FIRE WATER TANKS FOR COMMERCIAL, INDUSTRIAL AND MUNICIPAL APPLICATIONS

With over 123 years of history, CST is the firmly established leader in bolted and factory-welded steel tanks.

- > Constructed in 1/3 the time of field-welded - saving time and money
- > Dedicated Project Managers and Engineers - save time and reduce risks with dedicated professionals and integrated solutions
- > Meet or exceed NFPA 22, FM, USACOE and other industry standards
- > All CST tanks are factory coated in environmentally controlled conditions at ISO certified facilities
- > The GREEN alternative to field welded tanks - No VOC's

WORLD RECOGNIZED LEADER IN FIRE PROTECTION WATER STORAGE TANKS

CST Storage | 903 E 104th Street | Suite 900 | Kansas City | MO 64131 | +1-913-621-3700

